

Quarterly Visual

ACC-New Canton
VAG110048

3rd Quarter (Jul-Sep)

On 8/13/2020 at 11:00 AM

Outfall was sampled by BJ Barbrow

Nature of Discharge

Rain

Duration

11:00

Total Rainfall(in)

0.22

Time since previous event (HRS)

>72

Clarity

Clear

Odor

None

Floating Solids

None

Settle Solids

None

Foam

None

Oil Sheen

None

Any other indicators of Storm Water Pollution?


No

Visual quality of the receiving stream?

N/A

Comments and/or corrective actions taken (explain)

I CERTIFY UNDER PENALTY OF LAW THAT THIS DOCUMENT AND ALL ATTACHMENTS WERE PREPARED UNDER MY DIRECTION OR SUPERVISION IN ACCORDANCE WITH A SYSTEM DESIGNED TO ASSURE THAT QUALIFIED PERSONNEL PROPERLY GATHER AND EVALUATE THE INFORMATION SUBMITTED. BASED ON MY INQUIRY OF THE PERSON OR PERSONS WHO MANAGE THE SYSTEM OR THOSE PERSONS DIRECTLY RESPONSIBLE FOR GATHERING THE INFORMATION, THE INFORMATION SUBMITTED IS TO THE BEST OF MY KNOWLEDGE AND BELIEF TRUE, ACCURATE AND COMPLETE.



Larry W. Barbrow Jr.
Safety Environmental Manager